



Ultra-Power Sprayer®

Part# 4130, 4131, and 4132

Quick Start Guide for Ultra-Ever Dry

1. Use appropriate PPE (gloves, respirator, goggles, paint suit, etc.)
2. Prepare and clean surfaces prior to coating for better adhesion
3. Shake or mechanically mix the Bottom Coat for 5-10 minutes prior to application
4. Adjust the Ultra-Power Sprayer pattern to apply thin, even coats - do not pool the coating
5. Allow the Bottom Coat to dry for at least 30 minutes before applying the Top Coat (do not apply Top Coat if the Bottom Coat is still wet)
6. Clean the Ultra-Power Sprayer by spraying a small amount of xylene into a rag or waste container and allow the sprayer to dry before applying the Top Coat
7. Shake or mechanically mix the Top Coat for 3-5 minutes prior to application
8. Allow the Top Coat to dry for at least 30 minutes prior to challenging with liquid - allowing the Top Coat to dry longer (even overnight) can improve results
9. Clean the Ultra-Power Sprayer by spraying a small amount of xylene into a rag or waste container
10. Take apart and thoroughly clean all components of the Ultra-Power Sprayer gun with xylene and allow to air dry before storing
11. Dispose of xylene and cleaning materials according to local regulations
12. Clean the air filter on the back of the Ultra-Power Sprayer turbine after each use with water or compressed air
13. Refer to the specific instructions for Ultra-Ever Dry and the Ultra-Power Sprayer for more detailed information



UltraTech International, Inc.

1-904-292-1611

1-800-353-1611

www.UltraEverDry.com

11542 Davis Creek Court, Jacksonville, Florida 32256 USA

